CENTRAL INTELLIGENCE AGENCY

INFORMATION REPORT

This Document contains information affecting the National Defense of the United States, within the meaning of Title 18, Sections 793 and 794, of the U.S. Code, as amended. Its transmission or revelation of its contents to or receipt by an unauthorized person is prohibited by law. The reproduction of this form is prohibited.

	SECRET/CONTROL - U.S. SECURITY INFORMAT		25X1	
COUNTRY	Poland	REPORT		
SUBJECT	Jelcz Motor Vehicle Works	DATE DISTR.	1 May 195	i 3
		NO. OF PAGES	5	:
DATE OF INFO.		REQUIREMENT NO.	RD	0EV4
PLACE ACQUIRED		REFERENCES		25 X 1
		NEI EXTIACES		

This is UNEVALUATED Information

THE SOURCE EVALUATIONS IN THIS REPORT ARE DEFINITIVE.

THE APPRAISAL OF CONTENT IS TENTATIVE.

(FOR KEY SEE REVERSE)

25X1

- 1. The Jelez Motor Vehicle Works (Jelezanskie Zaklady Samochodowe) in Jelez (Jeltsch P62/C71), approximately 20 km. southeast of Wroclaw (Breslau), were built by the Germans during the war and completed in the beginning of 1943. The factory was known as the Berta Works and was a branch of Krupp in Essen. The plant repaired guns and armored vehicles for the German Army. After the war the plant was taken over by the Russians and was probably used for similar purposes. It was dismantled in 1948; the machines, except for a few large ones, were removed to the USSR
- 2. The plant remained in ruins until February 1952 and was then taken over by the MBP (Ministry of Public Security). At the same time the reconstruction work was started on the plant, a large prison camp, known as Budowa 315, was being constructed. The prison camp was to accommodate 10,000 prisoners; it was built exclusively by prisoners, approximately 1,200, and was completed in September 1952. It is believed that only prisoners with long sentences are to be brought to this camp.
- 5. Hall No. 2 of the factory was completed in April 1952, was equipped with machinery, and put into operation. Only repairs to trucks and building machinery are being carried out in this hall at present. Approximately 1,000 short-term prisoners are engaged in this work.

25 YEAR RE-REVIEW

SECRET/CONTROL - U.S. OFFICIALS ONLY


STATE	army ARMY	x	NAVY	ж	AIR	x	1831	AEC	ORR	Bv	x	
L									 		·	<u> </u>

(Note: Washington Distribution Indicated By "X"; Field Distribution By "#".)

570

SECRET/CONTROL - U.S. OFFICIALS ONLY 25X1

Sketch No. 1



SECRET/CONTROL - U.S. OFFICIALS ONLY

SECRET CONTROL - U.S. OFFICIALS ONLY

25X1

Legend to sketch No. 1.

- 1. Three-story houses for prisoners, each house with 18 dormitories containing 50 beds. In case of necessity even more beds can be put in.
- 2. Building with administration offices of the prison camp.
- 3. Entrance, guard and garages.
- 4. Prisoners cells.
- 5. Hospital.
- 6. Dining room with a theater; kitchen.
- 7. Laundry; baths; clothing store.
- 8. Food store.
- 9. Boiler house for central heating.
- 10. Flour store.
- 11. Bakery.

SECRET/CONTROL - U.S. OFFICIALS ONLY

SECRET CONTROL - U.S. OFFICIALS ONLY

SECRET CONTROL - U.S. OFFICIALS ONLY

25X1

SECRET/CONTROL - U.S.	OFFICIALS	ONLY	
- 5			
ng i			

Legend to sketch No. 2

- 1. Warehouse, 250 by 200 m., put into service in April 1952. The walls are of brick, the roof of wooden beams with artificial insulation plates with a double layer of roofing cardboard.
- 2. Workshop, 240 by 200 m., put into service in April 1952. The machinery is only used for repairs to brucks and building machines. The walls of the building are brick, the floor and the girders, concrete. The roof is as described above.
- 5. Factory hall under construction in summer 1952. The outside walls and cement pillars are ready. roof trusses of reinforced concrete, prefabricated sections, also concrete plates, are to be used as covering with roofing cardboard on top. The construction work is being carried out by civilian workers.
- 4. Hall, in ruins. I The walls and concrete pillars and approximately 50 percent of the roof still stand. No reconstruction work has been carried out to this hall. In the western extension, the former offices on the second floor are at present used as bedrooms, dining room, and sitting room for prison officials.
- 5. Hall, the major part of which is damaged; without roof and only part of the outside walls. At present the MBP construction office is located in the western extension of the building on the second floor.
- 6. Temporary buildings (with front extension of Hall No. 3) which at first served for administration purposes and also for accommodation of prisoners while the prison camp was under construction.
- 7. KBW (Internal Security Corps), quarters, approximately one company.
- 8. Water pumping station for the entire factory complex.
- 9. Former heating plant. The buildings, though in a good state of repair, are without equipment.
- 10. Projected summer living quarters for prison officials.
- 11. Pig sties.
- 12. Prison wall, 320 by 910 m. which surrounds Halls 2 and 3 and the prison camp.

 The wall is approximately 6 m. high, and the width is equal to two bricks; topped by broken glass. Watch towers are located at intervals of 80 to 100 m.; these are manned by members of the KBW.
- 13. Area mainly used for scrap trucks and buses.
- 14. Foundations for buildings originally planned by the Germans.

25X1

25X1

25X1

SECRET/CONTROL - U.S. OFFICIALS ONLY